



**GREATER CINCINNATI  
WATER WORKS**

A Service of The City of Cincinnati

**St. Teresa of Avila 1175 Overlook - Lead Testing Results**

SAMPLE DATE		SAMPLE TIME	LOCATION NAME	PARAMETER CODE	AMOUNT	COMMENTS	GCWW COMMENTS
6/1/2016	7:00 AM		STTERESA_PRIMARY#1	Lead, ppb	<1		St. Teresa of Avila School has been extremely proactive in understanding the water quality with the school. Personnel attended an informational meeting hosted by Greater Cincinnati Water Works and then followed the USEPA 3Ts for Reducing Lead in Drinking Water in Schools: Revised Technical Guidance Document (3Ts guidelines).
6/1/2016	7:00 AM		STTERESA_PRIMARY#2	Lead, ppb	1.05		
6/1/2016	7:00 AM		STTERESA_PRIMARY#3	Lead, ppb	<1		
6/1/2016	7:00 AM		STTERESA_PRIMARY#4	Lead, ppb	<1		
6/1/2016	7:00 AM		STTERESA_PRIMARY#5	Lead, ppb	1.29		
6/1/2016	7:00 AM		STTERESA_PRIMARY#6	Lead, ppb	<1		
6/1/2016	7:01 AM		STTERESA_PRIMARY#7	Lead, ppb	<1		
6/1/2016	7:01 AM		STTERESA_PRIMARY#8	Lead, ppb	1.45		
6/1/2016	7:02 AM		STTERESA_PRIMARY#9	Lead, ppb	1.23		
6/1/2016	7:02 AM		STTERESA_PRIMARY#10	Lead, ppb	3.11		
6/1/2016	7:05 AM		STTERESA_GROUND#1	Lead, ppb	1.23		While St. Teresa does not have a lead service line providing water to the school, lead was detected in various samples.
6/1/2016	7:05 AM		STTERESA_GROUND#2	Lead, ppb	9.03		
6/1/2016	7:05 AM		STTERESA_GROUND#3	Lead, ppb	2.63		
6/1/2016	7:10 AM		STTERESA_GROUND#4	Lead, ppb	1.48		
6/1/2016	7:10 AM		STTERESA_GROUND#5	Lead, ppb	2		
6/1/2016	7:10 AM		STTERESA_GROUND#7	Lead, ppb	13.2		
6/1/2016	7:10 AM		STTERESA_GROUND#8	Lead, ppb	1592	Not a tap used for consumption	
6/2/2016	7:00 AM		STTERESA_GROUND#6	Lead, ppb	689	Fixture taken out of service	
6/2/2016	7:00 AM		STTERESA_CAF#1	Lead, ppb	<1		Upon discussion with personnel at the school about the results, a remediation plan is now in place and includes steps such as taking fixtures out of service at various locations.
6/2/2016	7:00 AM		STTERESA_CAF#2	Lead, ppb	1.25		
6/2/2016	7:00 AM		STTERESA_CAF#3	Lead, ppb	86.9	Fixture taken out of service	
6/2/2016	7:00 AM		STTERESA_CAF#4	Lead, ppb	4.88		
6/2/2016	7:00 AM		STTERESA_GYM#1	Lead, ppb	7.02		Other steps in a remediation plan are being considered.
6/2/2016	7:15 AM		STTERESA_1STFLOOR#1	Lead, ppb	306	Fixture taken out of service	
6/2/2016	7:15 AM		STTERESA_1STFLOOR#2	Lead, ppb	<1		
6/2/2016	7:15 AM		STTERESA_1STFLOOR#3	Lead, ppb	<1		
6/2/2016	7:15 AM		STTERESA_1STFLOOR#4	Lead, ppb	1.61		
6/2/2016	7:15 AM		STTERESA_1STFLOOR#5	Lead, ppb	2.86		
6/2/2016	7:15 AM		STTERESA_1STFLOOR#6	Lead, ppb	1.74		
6/2/2016	7:15 AM		STTERESA_1STFLOOR#7	Lead, ppb	4.58		
6/2/2016	7:30 AM		STTERESA_2NDFLOOR#1	Lead, ppb	3		
6/2/2016	7:30 AM		STTERESA_2NDFLOOR#2	Lead, ppb	1.1		
6/2/2016	7:30 AM		STTERESA_2NDFLOOR#3	Lead, ppb	3.56		
6/2/2016	7:30 AM		STTERESA_2NDFLOOR#4	Lead, ppb	2.34		
6/2/2016	7:30 AM		STTERESA_2NDFLOOR#5	Lead, ppb	<1		
6/2/2016	7:30 AM		STTERESA_2NDFLOOR#6	Lead, ppb	<1		
6/2/2016	7:30 AM		STTERESA_2NDFLOOR#7	Lead, ppb	1.62		
6/2/2016	7:30 AM		STTERESA_2NDFLOOR#8	Lead, ppb	2.48		
6/2/2016	7:40 AM		STTERESA_2NDFLOOR#9	Lead, ppb	3.64		
6/2/2016	7:45 AM		STTERESA_SCIENCELAB	Lead, ppb	8.94		