

God's Bible School and College - Lead Testing Results

| # | SAMPLE DATE | SAMPLE TIME | SAMPLE NAME | PARAMETER CODE | AMOUNT | GCWW COMMENTS/REVIEW/RECOMMENDATIONS |
|----|-------------|-------------|--------------------|----------------|--------|---|
| 1 | 8/22/2016 | 30:00.0 | #1_GBS_SINK_1815#1 | Lead, ppb | <1 | Less than detection level |
| 2 | 8/20/2016 | 30:00.0 | #2_GBS_SINK_1815#2 | Lead, ppb | <1 | Less than detection level |
| 3 | 8/21/2016 | 20:00.0 | #1_GBS_SINK_1905#1 | Lead, ppb | <1 | Less than detection level |
| 4 | 8/20/2016 | 00:00.0 | #2_GBS_SINK_1905#2 | Lead, ppb | <1 | Less than detection level |
| 5 | 8/19/2016 | 45:00.0 | #3_GBS_SINK_1905#3 | Lead, ppb | <1 | Less than detection level |
| 6 | 8/20/2016 | 31:00.0 | #4_GBS_SINK_1905#4 | Lead, ppb | 1.27 | Less than 15ppb action level |
| 7 | 8/19/2016 | 00:00.0 | #5_GBS_SINK_1905#5 | Lead, ppb | <1 | Less than detection level |
| 8 | 8/19/2016 | 35:00.0 | #6_GBS_SINK_1905#6 | Lead, ppb | <1 | Less than detection level |
| 9 | 8/21/2016 | 05:00.0 | #7_GBS_SINK_1905#7 | Lead, ppb | <1 | Less than detection level |
| 10 | 8/29/2016 | 25:00.0 | #8_GBS_SINK_1905#8 | Lead, ppb | <1 | Less than detection level |
| 11 | 8/19/2016 | 40:00.0 | GBS_SINK_1930 | Lead, ppb | <1 | Less than detection level |
| 12 | 8/12/2016 | 00:00.0 | GBS_SINK_1908 | Lead, ppb | <1 | Less than detection level |
| 13 | 8/20/2016 | 25:00.0 | GBS_SINK_1902 | Lead, ppb | <1 | Less than detection level |
| 14 | 8/22/2016 | 25:00.0 | GBS_TUBFAUCET_1834 | Lead, ppb | 47.5 | High Lead Level. The USEPA 3Ts for Reducing Lead in Drinking Water in Schools: Revised Technical Guidance Document (3Ts Guidelines) recommends sampling drinking water and cooking outlets in schools. Conduct a plumbing profile to understand the material of the fixture at this sample point. Review 3Ts guidelines to understand options to reduce lead. If this sample point is used for drinking water or cooking purposes, until a remediation plan is created to address this high lead level, remove this location from service (tag out of service and/or turn off water supply to this location). |
| 15 | 8/21/2016 | 00:00.0 | #1_GBS_SINK_1832#1 | Lead, ppb | <1 | Less than detection level |
| 16 | 8/20/2016 | 27:00.0 | #2_GBS_SINK_1832#2 | Lead, ppb | <1 | Less than detection level |
| 17 | 8/20/2016 | 58:00.0 | #1_GBS_SINK_1837#1 | Lead, ppb | <1 | Less than detection level |
| 18 | 8/21/2016 | 39:00.0 | #2_GBS_SINK_1837#2 | Lead, ppb | <1 | Less than detection level |
| 19 | 8/20/2016 | 00:00.0 | #3_GBS_SINK_1837#3 | Lead, ppb | <1 | Less than detection level |

God's Bible School and College - Lead Testing Results

| # | SAMPLE DATE | SAMPLE TIME | SAMPLE NAME | PARAMETER CODE | AMOUNT | GCWW COMMENTS/REVIEW/RECOMMENDATIONS |
|----|-------------|-------------|---|----------------|--------|--------------------------------------|
| 20 | 8/21/2016 | 30:00.0 | #1_GBS_SINK_1803#1 | Lead, ppb | <1 | Less than detection level |
| 21 | 8/20/2016 | 16:00.0 | #2_GBS_SINK_1803#2 | Lead, ppb | <1 | Less than detection level |
| 22 | 8/21/2016 | 35:00.0 | #3_GBS_SINK_1803#3 | Lead, ppb | <1 | Less than detection level |
| 23 | 8/21/2016 | 05:00.0 | #4_GBS_SINK_1803#4 | Lead, ppb | 5.54 | Less than 15ppb action level |
| 24 | 8/21/2016 | 45:00.0 | GBS_SINK_532 | Lead, ppb | 1.1 | Less than 15ppb action level |
| 25 | 8/20/2016 | 15:00.0 | GBS_DRINKINGFOUNTAIN_LIBRARY | Lead, ppb | 1.05 | Less than 15ppb action level |
| 26 | 8/21/2016 | 00:00.0 | #1_GBS_SINK_537#2MOS | Lead, ppb | 4.58 | Less than 15ppb action level |
| 27 | 8/22/2016 | 00:00.0 | GBS_SINK_511RING | Lead, ppb | <1 | Less than detection level |
| 28 | 8/21/2016 | 25:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_GIRLS2ND | Lead, ppb | <1 | Less than detection level |
| 29 | 8/20/2016 | 40:00.0 | GBS_CAMPUS_WATERFOUNTAIN_STUCTRGYM | Lead, ppb | <1 | Less than detection level |
| 30 | 8/21/2016 | 40:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_ACA | Lead, ppb | <1 | Less than detection level |
| 31 | 8/21/2016 | 45:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_HIGHSCHOOL | Lead, ppb | <1 | Less than detection level |
| 32 | 8/22/2016 | 29:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_BOYS1STRESSID | Lead, ppb | <1 | Less than detection level |
| 33 | 8/20/2016 | 45:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_STUCTRBAND | Lead, ppb | 1.19 | Less than 15ppb action level |
| 34 | 8/22/2016 | 31:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_BOYS1STFACSIDE | Lead, ppb | <1 | Less than detection level |
| 35 | 8/20/2016 | 30:00.0 | GBS_CAMPUS_SINK | Lead, ppb | <1 | Less than detection level |
| 36 | 8/21/2016 | 23:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_GIRLS-3RD | Lead, ppb | 3.93 | Less than 15ppb action level |
| 37 | 8/22/2016 | 36:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_BOYS3RD | Lead, ppb | <1 | Less than detection level |
| 38 | 8/22/2016 | 45:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_FACILITIES | Lead, ppb | <1 | Less than detection level |
| 39 | 8/22/2016 | 25:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_BOYS-3RD | Lead, ppb | <1 | Less than detection level |
| 40 | 8/21/2016 | 21:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_GIRLS4TH | Lead, ppb | <1 | Less than detection level |
| 41 | 8/20/2016 | 45:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_MUSIC | Lead, ppb | <1 | Less than detection level |
| 42 | 8/21/2016 | 27:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_GIRLS1ST | Lead, ppb | <1 | Less than detection level |
| 43 | 8/22/2016 | 34:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_BOYS2ND | Lead, ppb | <1 | Less than detection level |
| 44 | 8/20/2016 | 35:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_STUCTRFRONT | Lead, ppb | 1.67 | Less than 15ppb action level |
| 45 | 8/20/2016 | 38:00.0 | GBS_CAMPUS_DRINKINGFOUNTAIN_STUCTRSNACKSHOP | Lead, ppb | 2.43 | Less than 15ppb action level |

God's Bible School and College - Lead Testing Results

| # | SAMPLE DATE | SAMPLE TIME | SAMPLE NAME | PARAMETER CODE | AMOUNT | GCWW COMMENTS/REVIEW/RECOMMENDATIONS |
|----|-------------|-------------|-------------------|----------------|--------|---|
| 46 | 8/22/2016 | 10:00.0 | GBS_SINK_538 | Lead, ppb | 30.1 | High Lead level. Until a remediation plan is created to address this high lead level, remove this location from service (tag out of service and/or turn off water supply to this location). Conduct a plumbing profile to understand the material of the fixtures at this sample point. Review 3Ts guidelines to understand options to reduce lead. |
| 47 | 8/20/2016 | 23:00.0 | GBS_SINK_535CH | Lead, ppb | <1 | Less than detection level |
| 48 | 8/22/2016 | 00:00.0 | GBS_SINK_531 | Lead, ppb | <1 | Less than detection level |
| 49 | 8/21/2016 | 20:00.0 | GBS_SINK_525 | Lead, ppb | <1 | Less than detection level |
| 50 | 8/22/2016 | 00:00.0 | GBS_SINK_523 | Lead, ppb | <1 | Less than detection level |
| 51 | 8/19/2016 | 36:00.0 | #1_GBS_SINK_518#1 | Lead, ppb | <1 | Less than detection level |
| 52 | 8/21/2016 | 00:00.0 | GBS_SINK_544 | Lead, ppb | <1 | Less than detection level |
| 53 | 8/29/2016 | 34:00.0 | #9_GBS_SINK_511#9 | Lead, ppb | <1 | Less than detection level |
| 54 | 8/21/2016 | 30:00.0 | GBS_SINK_516 | Lead, ppb | 1.38 | Less than 15ppb action level |
| 55 | 8/22/2016 | 00:00.0 | GBS_SINK_520 | Lead, ppb | <1 | Less than detection level |
| 56 | 8/22/2016 | 28:00.0 | GBS_SINK_522 | Lead, ppb | 1.96 | Less than 15ppb action level |
| 57 | 8/21/2016 | 55:00.0 | #2_GBS_SINK_518#2 | Lead, ppb | <1 | Less than detection level |
| 58 | 8/22/2016 | 2:27 | GBS_SINK_1904 | Lead, ppb | 2.06 | Less than 15ppb action level |