

### Holy Family Catholic School- Lead Testing Results

SCHOOL	SAMPLE DATE	SAMPLE NAME	PARAMETER CODE	AMOUNT OF LEAD	GCWW COMMENTS/REVIEW/RECOMMENDATIONS REGARDING RESULTS
Holy Family	9/14/2016	HOLYFAM_WTRFTNSCHOOLOFFICE	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_KITCHENSINKII	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_PCKITCHENSINK	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_KITCHENSINKI	Lead, ppb	1.47	Less than 15ppb action level. Conduct a plumbing profile to understand the material of the fixtures at sample point. Review 3Ts Guidelines to understand options to reduce the risk of lead.
Holy Family	9/14/2016	HOLYFAM_KITCHENSINKDW	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_CAFEWTRFTN	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_SINKOFFICESCH	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_GRANDHALLWTRFTN	Lead, ppb	1.05	Less than 15ppb action level. Conduct a plumbing profile to understand the material of the fixtures at sample point. Review 3Ts Guidelines to understand options to reduce the risk of lead.
Holy Family	9/14/2016	HOLYFAM_PRE-SCH	Lead, ppb	1.97	Less than 15ppb action level. Conduct a plumbing profile to understand the material of the fixtures at sample point. Review 3Ts Guidelines to understand options to reduce the risk of lead.
Holy Family	9/14/2016	HOLYFAM_WTRFTNARTROOM	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_RRNURSESSTATION	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_WTRFTNGYM	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_LOUNGESCH	Lead, ppb	<1	Less than detection level
Holy Family	9/14/2016	HOLYFAM_HCHKTCHNSINK	Lead, ppb	<1	Less than detection level

### Holy Family Catholic School- Lead Testing Results

SCHOOL	SAMPLE DATE	SAMPLE NAME	PARAMETER CODE	AMOUNT OF LEAD	GCWW COMMENTS/REVIEW/RECOMMENDATIONS REGARDING RESULTS
Holy Family	9/14/2016	HOLYFAM_SINK-GYMCLUB	Lead, ppb	5.63	Less than 15ppb action level. Conduct a plumbing profile to understand the material of the fixtures at sample point. Review 3Ts Guidelines to understand options to reduce the risk of lead.
Holy Family	9/14/2016	HOLYFAM_GYMCLUBWTRFTN	Lead, ppb	1.48	Less than 15ppb action level. Conduct a plumbing profile to understand the material of the fixtures at sample point. Review 3Ts Guidelines to understand options to reduce the risk of lead.
Holy Family	9/14/2016	HOLYFAM_SAC-CHRSINK	Lead, ppb	3.37	Less than 15ppb action level. Conduct a plumbing profile to understand the material of the fixtures at sample point. Review 3Ts Guidelines to understand options to reduce the risk of lead.
Holy Family	9/14/2016	HOLYFAM_PANTRYSink	Lead, ppb	<1	Less than detection level